

Cómo Programar una Inspección en CSS

<https://amarillotx-energopub.tylerhost.net/Apps/SelfService#/home>

Hay dos lugares para pedir una inspección:

En la etiqueta "Summary":

- Seleccione "Request" en el cuadro "Available Actions"

The screenshot displays the eReviews portal interface for a permit. At the top, there is a navigation bar with links for Dashboard, Apply, Home, My Work, Map, Report, Search, and Calendar. Below the navigation bar, the permit number BLDR-21-000393 is shown. A notification banner indicates that Internet Explorer 11 is required. The main content area shows permit details in a light blue box, including Type (Building Residential - Roofing), Status (Issued), Project Name, IVR Number (101630), Applied Date (04/30/2021), Issue Date (04/30/2021), District (Building Safety), Assigned To, Expire Date (10/27/2021), Square Feet (0.00), and Finalized Date. Below the details is a tabbed interface with 'Summary' selected. The Summary tab contains three panels: 'Progress' showing a 67% completion donut chart, 'Workflow' showing a list of steps like 'Confirm Application Complete' and 'Issue Permit', and 'Available Actions' which includes a 'Request Inspection' button with a 'Request' sub-button highlighted by a red box.

Dashboard Apply Home My Work Map Report Search Calendar

Permit Number: BLDR-21-000393

Internet Explorer 11 is required to use the eReviews portal.

Permit Details | Tab Elements | Main Menu

Type:	Building Residential - Roofing	Status:	Issued	Project Name:	
IVR Number:	101630	Applied Date:	04/30/2021	Issue Date:	04/30/2021
District:	Building Safety	Assigned To:		Expire Date:	10/27/2021
Square Feet:	0.00	Finalized Date:			
Description:	Remove and replace roof				

Summary Locations Fees Inspections eReviews Attachments Contacts Sub-Records More Info

Progress

67% Completed

- Completed
- In Progress
- Not Started

Workflow

- Confirm Application Complete - Passed: 04/30/2021
- Issue Permit - Passed: 04/30/2021
- Final Building -

Available Actions

Request Inspection
Final Building

Request

O en la etiqueta "Inspections"

- Marque la caja bajo "Action" por la inspección
- Seleccione "Request Inspection"

The screenshot shows the Tyler Citizen Self Service portal interface. At the top, the Tyler logo and "Citizen Self Service" are visible. The user is logged in as "Good Afternoon, Building Safety" with a notification icon for 1 item. The language is set to "English (United States)". The navigation bar includes "Dashboard", "Apply", "Home", "My Work", "Map", "Report", "Search", and "Calendar".

The main content area displays "Permit Number: BLDR-21-000393". Below this, a message states "Internet Explorer 11 is required to use the eReviews portal." The "Permit Details" section includes the following information:

Type:	Building Residential - Roofing	Status:	Issued	Project Name:	
IVR Number:	101630	Applied Date:	04/30/2021	Issue Date:	04/30/2021
District:	Building Safety	Assigned To:		Expire Date:	10/27/2021
Square Feet:	0.00	Finalized Date:			
Description:	Remove and replace roof				

Below the permit details, there are several tabs: "Summary", "Locations", "Fees", "Inspections" (highlighted with a red box), "Reviews", "Attachments", "Contacts", "Sub-Records", and "More Info".

The "Existing Inspections" section shows a table with columns: "View Inspection", "Description", "Status", "Request Date", "Scheduled Date", "Inspector", and "Action". The table is currently empty, with the message "No records to display." Below this, the "Request Inspections" section is visible, with a table that has columns: "Description", "Reinspection", "Action", and "Sort". The table contains one row with the following data:

Description	Reinspection	Action	Sort
Final Building	No	<input checked="" type="checkbox"/>	Order

At the bottom right of the "Request Inspections" section, there is a "Request Inspection" button (highlighted with a red box). The "Results per page" is set to 10, and the current page is 1 of 1.

Rellene "Nombre de contacto". "Teléfono de contacto" y "Fecha solicitada". Si corresponde, agregue "Comentarios/Código de puerta". Seleccione "Submit"

The screenshot shows the Tyler Citizen Self Service portal interface for the "Request Inspections" form. The Tyler logo and "Citizen Self Service" are visible at the top. The user is logged in as "Good Afternoon, Building Safety" with a notification icon for 1 item. The language is set to "English (United States)". The navigation bar includes "Dashboard", "Apply", "Home", "My Work", "Map", "Report", "Search", and "Calendar".

The main content area displays "Request Inspections (1)". Below this, there is a "Back" link. The form is titled "Request Inspections (1)" and includes a "REQUIRED" label. The form contains the following fields:

- Inspection Type: Final Building
- Case Type: Building Residential - Roofing
- Address: 806 S BUCHANAN ST Amarillo, TX
- * Contact Name:
- * Contact Phone:
- * Requested Date:
- Comments/Gate Code:

At the bottom right of the form, there is a "Submit" button (highlighted with a red box).

La confirmación de la inspección será una marca verde. Seleccione "Back"

The screenshot shows the Tyler Citizen Self Service interface. At the top, there is a navigation bar with the Tyler logo and 'Citizen Self Service technologies'. The user is logged in as 'Building Safety' and the language is set to 'English (United States)'. The main navigation menu includes 'Dashboard', 'Apply', 'Home', 'My Work', 'Map', 'Report', 'Search', and 'Calendar'. A red box highlights a 'Back' button in the top left corner. Below the navigation, the page title is 'Request Inspections (1)'. A red asterisk and the word 'REQUIRED' are visible in the top right. The main content area displays details for Case #BLDR-21-000393. The details include: Inspection Type: Final Building; Case Type: Building Residential - Roofing; Address: 808 S BUCHANAN ST Amarillo, TX; Requested Date: 05/03/2021; Comments/Gate Code; Contact Name: Building Safety; Contact Phone: (806) 378-3041. A green checkmark icon is highlighted with a red box at the bottom of the case details.

En la etiqueta "Inspection" está disponible el número de inspección, la fecha programada y el inspector asignado.

The screenshot shows the Tyler Citizen Self Service interface for permit details. The permit number is BLDR-21-000393. A message indicates that Internet Explorer 11 is required for the eReviews portal. The permit details are as follows:

Type:	Building Residential - Roofing	Status:	Issued	Project Name:	
IVR Number:	101630	Applied Date:	04/30/2021	Issue Date:	04/30/2021
District:	Building Safety	Assigned To:		Expire Date:	10/27/2021
Square Feet:	0.00	Finalized Date:			
Description:	Remove and replace roof				

Below the details, there is a navigation bar with tabs: Summary, Locations, Fees, Inspections (highlighted with a red box), eReviews, Attachments, Contacts, Sub-Records, and More Info. Below the tabs, there is a table of existing inspections:

View Inspection	Description	Status	Request Date	Scheduled Date	Inspector	Action
IBLD-2021-00806	Final Building	Requested	05/03/2021	05/03/2021	Downing Robert	

At the bottom, there is a pagination control showing 'Results per page 10' and '1 - 1 of 1' with navigation arrows.